**	Approved For Release 2002/08/16 CIA-RDP66B0072	28R000300050051	6077777
	THE FIRST CO. THE COLUMN TO A	1 /D-05/	13 DIFA
STE	2212Z 22 MAY 63 SECRET	3	6 //
25X1A	The state of the s	and speed speed of the speed of	OP
ing a gapantang salah andaran ta ing apat ang pana Panan tahun at Manda	DIRECTOR		CD SD
70 I			Ŕ
FROM	25X1A (1-15)		KB
ACTION	. OSA(1-15)	F	ROUTINE
nro .	:5/C (16) 25X1A (10) 3502	Particularly, and placed properly and to proceed a common matter.	
	7647 there l	t	IN 77399
25X1A		elds.	25X1A
e consistence of the constitution of the const	TOR: 23422 22 MAY 63 M dut	him	
ខា	25X1A	194	6811
•	REF: A. 3892 DOCUMENT NO. HO CHANGE IN CLASS	·	
25X1A	B. 7642 V CLASSI BRANCIAL TO:	78 8 0 //	
25X1A -	COL LEDFORD FROM KELLY JOHNSON ASTR: NR 12-2		25X1A
	DISCREPANCIES NOTED IN REF A DUE TO WORK	MANSHIP AND	INSPECTION
•			
	NOT FLIGHT CHECK. AMTICLE 350 FLOWN TOTAL FO		COMPLETION
	OF IRAN. ALL FLIGHTS NORMAL INCLUDING AUTOPI	ILOT.	
	THE FOLLOWING COMMENTS ARE OFFERED TO REF A:		25X1A
	ITEM I A - OMMISSION OF HOLES IN POD FOR	R EQUIPMENT M	OUNT ING
(DISCOVERED DAY OF DELIVERY. TOOK CO	RRECTIVE ACTI	ON: SENT
25X1A	CREW TO TO DRILL HOLES.		
	ITEM 1 B - NO EXCUSE FOR THIS CONDITION	. THIS IS-A	PREFLIGHT
·	INSPECTION ITEM.		
	ITEM 1 C - THIS APPEARS TO BE THE RESULT	T OF POOR WOR	KMANSHIP
25X1A	AND INSPECTION.		
	ITEMS 1 4, B AND C HAS TAKEN CORRECT	IVE ACTION TO	PREVENT
	REOCCURRANCE.		
25X1A	ITEM 2 A - DOES MINIMUM MAINTEN	ANCE ON DRIFT	
	THESE MAINTAINED BY PERSONNEL AT	CROSP 1	25X1A
	SECRET	downgrating and	· · · · · · · · · · · · · · · · · · ·
	REPRODUCTION BY CITER IT AN CHE ISRUING COPIC	S IS PROHIBITED	Copy Ma

Approved For Release 2002/08/16: CIA-RDP66B00728R000300050051-6

25X1A	SECRET	25X1A	
٠,	S811 (IN 77399) PA	GE -2-	
	ITEM 2 8 - AUTOPILOT OPERATED SUCCESSFULLY AT	DURING	
	ALL FLIGHTS. AUTOPILOT REP WAS SENT TO DISCOV	ERED 25X1A	
	INTERMITTENT CONTACT AT EXTREME TRAVEL OF ROLL POT. THIS WAS A		
	GROUND CHECK-OUT SQUAVE. NORMALLY, IN FLIGHT, POT WOULD	FLIGHT, POT WOULD NEVER	
25X1	TRAVEL TO EXTREME. CONDITION FIXED AND ARTICLE SUCCESSFU	LLY FLOWN. T. ARTICLE	
	REFLOWN YESTERDAY, MAY 21, CONDITION COULD BE REPEATED ONLY AFTER		
	FOUR SUCCESSFUL CHANGEOVERS. CONTROL BEING CHANGED. ART	ICLE WILL BE	
200	REFLOWN. FUEL CONTROL TO BE INSPECTED IN DETAIL TO DETERMINE CAUSE		
	OF PROBLEM. REPORT WILL FOLLOW.		
Ĺ	RENCE 25X1A		
	WAS CAUSED BY LACK OF ADEQUATE CLEARANCE. THIS DISCOVERE	D AT	
	AFTER SECOND FLIGHT. REPAIR MADE AND SPEED BRAKE OPERATED ON GROUND.		
	REFLOWN AND CHECKED O.K. REOCCURRANCES AT REQUI	RED OUR REP	
!	TO READJUST SPEED BRAKE AT HINGE.	25X1A	
,			

END OF MESSAGE

SECRET